


Annie Arterial Insufficien<u>cy Leg™ – 0555</u>

The following conditions* are represented on Annie Arterial Insufficiency Leg™



* Some of the conditions represented on this model may appear different on individual patients, yet still be considered the same condition. The representation of the conditions we have chosen to display are based on feedback from wound care professionals.

Care Instructions: To clean your model VATA recommends soap and warm water.

308 South Sequoia Parkway			I Canby, Oregon 97013 USA			
ph. 503.651.5050	fax 503.651.50	052 I w	ww.vatainc.com	I	email	info@vatainc.com